PRODUCT DATA SHEET HAYMES DERUSTIT





GENERAL DESCRIPTION

A phosphoric acid based rust removal treatment for metal surfaces.

<u>USES</u>

To remove rust and corrosion products from metal surfaces to prepare a clean surface ready for paint application. Suitable metal surfaces including cast wrought iron and mild steel. **Not suitable for use on zinc or cadmium plated metals.**

<u>SIZES</u>

Available in 500ml, 1 litre, 4 litres and 24 litres.

COVERAGE

Coverage of up to 17 square meters per litre depending upon surface roughness.

APPLICATION TOOLS

Brush. PROVIDE ADEQUATE VENTILATION DURING USE.

DRYING TIMES

Touch Dry Time – 30 minutes. Recoat Dry Time - 16 hours. Drying times refer to normal conditions (25°C, 50% humidity). Under cooler, humid or still conditions, longer drying times may be necessary.

DO NOT USE IN TEMPERATURES BELOW 10°C OR ABOVE 30°C.

DANGEROUS GOODS CLASSIFICATION

Class 8 Corrosive Liquid, Acidic, Inorganic N.O.S. UN 3264 Packaging Group III S5 Poison

	QUICK CHECK
۵	Interior/Exterior
ī	Water Wash Up
S	Brush
	Recoat – 16 hours

SURFACE PREPARATION:

Wire brush or scrape surface to remove any loose flaking corrosion build up. Brush apply one liberal coating of Haymes Derustit without dilution and allow to dry for 16 hours. If corrosion deposits are heavy, wire brushing may be required to assist penetration. After drying, dust off with a clean dry brush. **Do not allow water to contact surface before priming**.

FINISHING

Apply 2 coats of Haymes Metal Primer and allow to dry for 24 hours. Finish with 2 coats of your selected topcoat.

CLEAN UP

Clean equipment with water immediately after use.

COATING CONDITIONS

Do not apply if the temperature is below 10°C or above 30°C. While in hot weather, avoid painting in direct sunlight. Avoid applying externally in late afternoon in winter or in doubtful weather as frost, dew or rain is likely to impair gloss or durability of the coating. Use away from naked flames.

STORAGE

Protect from extremes of temperature. Store between 5° C and 30° C.

PRECAUTIONS

- <u>Safety & First Aid Directions:</u> Use protective clothing, gloves and eye goggles. Provide adequate ventilation with sufficient air flow for a comfortable working atmosphere. In enclosed areas use an approved acid gas air purifying respirator with mist filter. If swallowed DO NOT INDUCE VOMITING drink plenty of water and seek immediate medical advice and show container or label. Contact a Doctor or Poisons Information Centre (Phone 131126). If skin contact occurs, remove contaminated clothing and wash skin thoroughly with soap and water. If irritation occurs seek prompt medical advice. In case of eye contact, hold eyes open and flood with running water for at least 15 minutes seek medical advice if irritation persists. *KEEP OUT OF REACH OF CHILDREN*.
- Protect Our Environment: DO NOT pour left over product down the drain. Retain it in a marked sealed container for future use or disposal via chemical waste collection programs. Do not re-use empty containers.

For best results, preparation is vitally important when repainting. Always ensure that the adhesion of old paint is sound before proceeding.

For further information or to place an order, call Service Express direct: Phone - 1800 033 431 or email at - www.havmespaint.com.au