

Manufacturers of UTHANE Polyurethane Coatings 14a Williamson Road, Ingleburn, NSW, 2565 Phone +612 9729-2000 1300 BCC OAT (222 628)

> Email: <u>orders@bccoatings.com.au</u> Text Orders/Enquiries: 0487 800 090

TECHNICAL DATA SHEET

PRODUCT PAINT STRIPPER

DESCRIPTION High grade, non-flammable, fast acting paint remover

for metal and wood.

Does not require neutralizing.

DRYING CYCLE Fast acting - for best results avoid using in hot sunshine or when

exposed to windy conditions.

SURFACE PREPARATION / APPLICATION GUIDE

Flow on a heavy, even coat of paint stripper using a soft bristle brush.

Stroke the brush in one direction only.

If applied by spray, open nozzle wide to assure heavy, even coat.

Let stand until old finish is blistered completely or softened sufficiently

for removal.

Do **NOT** rush the job.

Let the paint stripper do the work.

Remove old finish with painter's scraper, steel wool or rags.

No "after-wash" or "neutralizing" necessary.

Will safety remove paint, enamel, lacquer, shellac, plastic, varnish, etc.

from wood metal, plaster or masonry.

Specially recommended for overhead or vertical surfaces.

Will not remove stain from timber or raise the grain.

Do **NOT** use on vinyl or plastic.

WARNING Volatile solvent.

Use with adequate ventilation.

Avoid prolonged or repeated breathing of vapour. Avoid prolonged or repeated contact with the skin.

Do **NOT** take internally.

If paint stripper causes skin to smart or burn, wash off

IMMEDIATELY with clear water.



Manufacturers of UTHANE Polyurethane Coatings 14a Williamson Road, Ingleburn, NSW, 2565 Phone +612 9729-2000 1300 BCC OAT (222 628)

> Email: <u>orders@bccoatings.com.au</u> Text Orders/Enquiries: 0487 800 090

TECHNICAL DATA SHEET PAINT STRIPPER

FIRST AID TREATMENT

INHALATION Remove victim from exposure into air.

Get urgent medical attention.

If breathing has stopped, apply artificial respiration.

If breathing laboured, apply oxygen.

If cardiac arrest occurs, apply external cardiac massage.

INGESTION If more than 15 minutes from hospital, induce vomiting,

preferably using Ipecac Syrup APF.

Avoid giving milk or oils.

Give water to drink.

Do not attempt to induce vomiting in an unconscious person.

Get medical attention urgently.

EYES Hold eyelids open and flood with water for at least 15 minutes.

Get medical attention.

SKIN Remove contaminated clothing and wash thoroughly with soap and water.

Wash contaminated clothing before re-use.

PACKAGED IN 4 Litres, 1 Litre

This data sheet is based on information in BC Coatings possession at date of issue.

BC Coatings supplies its products only on condition that the consumer is satisfied as to the performance of the product in meeting his particular requirements.

Date Of Issue: 01/02/2017 Page 2 of 2 TDS00079 V2